


KEY



Proposed trees for retention, tree work to be carried out by arboriculturalist



Proposed trees for removal, under the guidance of arboriculturalist



edge of park as buffer to cemetery



existing fence line relocated to align more with original boundary of cemetery.

1. reinstate /open up original entrance to pioneer section of cemetery
2. upgrade and formalise the Lych-gate entrance to the cemetery, review the structure and repair as necessary.
3. review internal path network within cemetery and ensure that paths are not travelling over top of unmarked graves. Review surface material width and restore original connections where possible.
4. carry out tree work on Elms along the southern boundary as these trees sit outside the burial ground, once removed realign fence to known earlier location. This will provide a 'buffer' between the park, the parking and the cemetery. Front of the cemetery, to be maintained as park land.
5. tidy up area and add 3 car parks.
6. Interpretation cottage - place old shed in new location by 'main gates' to cemetery. The area will require detailed design and documentation to resolve interpretation strategy.
7. Realign entrance to cemetery and reduce width to single vehicle width, detailed design of entrance to be confirmed.



**OPTION ONE**  
 QUEEN ELIZABETH PARK - pioneer section of Masterton Cemetery  
 preliminary concept plan